


Separate Type $\varnothing 25$ mm



*Please maintain not to exceed speed limit. Excess speed will dramatically reduce bearing life.

*1 : Maximum rotating speed at the cutting tool. *2 : Maximum allowable motor speed for the spindle.