



***Please maintain not to exceed speed limit. Excess speed will dramatically reduce bearing life.**

*1 : Maximum rotating speed at the cutting tool. *2: Maximum allowable motor speed for the spindle.