


Separate Type  $\varnothing 30$  mm



\*Please maintain not to exceed speed limit. Excess speed will dramatically reduce bearing life.

\*1 : Maximum rotating speed at the cutting tool.

\*2: Maximum allowable motor speed for the spindle.